

REDx Developer Kit Data Update

● Firmware

- 1) RED4 Firmware(v2.5.0) → [RED4 Firmware\(v2.5.1\)](#)
- 2) RED5 Firmware(v2.5.0) → [RED5 Firmware\(v2.5.1\)](#)
 - Updated Leakage Calibration Library
 - Fixed bug about AutoReadEx Function
 - Fixed bug when using I2C interface
 - Fixed Write Function Error
 - Fixed 'Smart Optimum Hopping Table' Error
 - Fixed 'Read Type C Long Data' Error
 - Fixed Minor Bug

● GUI

- 1) RED Utility(v2.5.0) → [RED Utility\(v2.5.2\)](#)
 - Fixed Region description of the RCP Decoder
 - Fixed Minor Bug

● Manual of Module, Chip

- 1) Reader Control Protocol User Manual(v1.0.10)
→ [Reader Control Protocol User Manual\(v1.0.11\)](#)
 - Removed in section 4.32 Stop Auto Read RSSI
- 2) Developer Kit Utility User Manual(v1.0.5)
→ [Developer Kit Utility User Manual\(v1.0.6\)](#)
 - Added mention of the Sensor tag function

● Application Note

- 1) Sensor Tag Application(v01) → [Sensor Tag Application\(v02\)](#)
 - Updated Image
 - Updated RCP Packet

Dated October 6, 2016